

# HILLHURST OFFICE/RETAIL REHAB

Los Angeles, California

5,000 square foot masonry two story office/retail building constructed in 1926 required seismic structural upgrade and common space interior design for the second floor offices. Second floor office doors were highlighted with irregular shaped wood floor entry “mats” and metal and plastic canopies. Wall lighting was encased in sloping sano tubes connected by metal conduit exposed on the wall.

